



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 26663



WO #: 26663

Customer: 93198 - MILLSAPS, JOE
 Address: 106 DISSTON RD
 OAK RIDGE, TN
 37830
 Home Phone: (865) 263-1912
 Work Phone:
 Author: S.DAVIS
 Location: IH
 Invoice #:

Stock #: 11005
 Stock Desc: 2025 CT FOREST RIVER
 ROCKWOOD CAMP A213HS
 Model: A213HS
 Serial #: 4X4CPRW14SD320764
 Chassis #:
 Mileage:
 Key #: 1500
 Req'n #:
 License #:
 Trim:

Purchase Date: 20 SEP 25
 Date In: 23 JAN 26
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed: 07 FEB 26
 Warr. Date: 20 SEP 25

Job #1 - Warranty

COMPLAINT: MAXXAIR VENT COVER CRACKED IN THE MIDDLE

CAUSE: COVER DEVELOPED CRACKS

CORRECTION: REMOVE CURRENT MAXXAIR COVER, CLEAN ALL SEALANT IN AREA, REPLACE WITH NEW COVER AND THEN RESEAL AREA

LABOR .50

Labor

Job #	Description	Hours	Total
1	REPLACED COVER	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
F100443645	ROOF VENT PART - 2E-4: MAXXAIR FAN, DOME LID FOR MODEL# 00-04401MX - V# 05-04401	1.00	63.60	63.60

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	19.43	19.43

Subtotal for Job #1: 170.53

Parts Total: 63.60
 Labour Total: 87.50
 Sublet Total: 0.00
 Extras Total: 19.43
WORK ORDER TOTAL: 170.53

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 07 Feb 2026

Customer #: 93198
 MILLSAPS, JOE

