



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26727



WO #: 26727

Customer: 91325 - MUSE, PATRICK
Address: 373 TRIMONT TRAIL APT 5
FRANKLIN, NC
28734

Home Phone: 828-371-5461

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 10922
Stock Desc: 2024 TT KZ-RV CONNECT 302FBK
Model: 302FBK
Serial #: 4EZTL3222R4030335
Chassis #:
Mileage:
Key #: 9690
Req'n #:
License #:
Trim:

Purchase Date: 10 DEC 24
Date In: 14 FEB 26
Promise Date:
Promise Time:
Schedule Date:
Completed: 04 MAR 26
Warr. Date: 10 DEC 24

Job #1 - Warranty

COMPLAINT: OUR DOOR GRIDDLE IS LEAKING GREASE WHEN CUSTOMER IS USING IT.

CAUSE: GRIDDLE IS FAULTY AND CRACKED ALLOWING HOT GREASE TO LEAK FROM GRIDDLE WHILE CUSTOMER USES.

CORRECTION: REPLACE GRIDDLE
LABOR 1.0

Labor

Job #	Description	Hours	Total
1	REPLACE GRIDDLE TOP	0.70	122.50

Parts

Part #	Description	Qty	Price	Total
164478	PLATE ONLY,F/COOKTOP,GRIDDLE,OUTDO OR,WITH PERMENANT GAS CONNECTION,^^ORDER PART 164477 COOKTOP GRIDDLE ALSO^^	1.00	78.00	78.00

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	16.92	16.92

Subtotal for Job #1: 217.42

Parts Total:	78.00
Labour Total:	122.50
Sublet Total:	0.00
Extras Total:	16.92
WORK ORDER TOTAL:	217.42

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 91325
MUSE, PATRICK



Customer Signature : _____

Date: 04 Mar 2026

W/O: 26727



Customer #: 91325
MUSE, PATRICK



Customer Work
Order

