



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26869
Promised Date:
26 MAR 26



WO #: 26869 (Appointment Date: 24 MAR 2026 - Time: 09:00am)

Customer: 93635 - MILLER, BENJAMIN
Address: 236 HIGH ROCK RD
ROGERSVILLE, TN
37857

Home Phone:

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11142

Stock Desc: 2026 TT DUTCHMEN ASPEN TRA

MINI 17BH

Model: 17BH

Serial #: 4YDTATG1XT8920098

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 30 JAN 26

Date In: 21 MAR 26

Promise Date: 30 MAR 26

Promise Time: 09:00am

Schedule Date:

Completed: 30 MAR 26

Warr. Date: 30 JAN 26

Job #1 - Warranty

COMPLAINT: BURNER ASSEMBLY ON REAR EYE TURNS OFF AFTER 20 SEC WHEN SOMETHING IS OVER IT IE A COFFEE POT

CAUSE: TECH VERIFIED THE THERMO COUPLER WAS BENT UP TO THE BURNER. THIS WAS CAUSING THE BURNER ASSEMBLY TO TURN OFF.

CORRECTION: ADJUST THE THERMO COUPLER AWAY FROM BURNER AND TEST
LABOR AND DIAG .50

Labor

Job #	Description	Hours	Total
1	ADJUSTED THERMO COUPLER	0.50	87.50
Subtotal for Job #1:			87.50

Parts Total: 0.00
Labour Total: 87.50
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 87.50

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 93635
MILLER, BENJAMIN



Customer Signature : _____

Date: 30 Mar 2026

